

**CLUTCHTECH**



## TSB - CAS01

Models applicable > Case 385 to > 885

Details > with 280mm (Split>Torque) cover assembly  
Ag Clutch Part Numbers > 128 1001 CA and 628 1002 CA  
Clutch plate and PTO hub alignment >

Use of the correct clutch aligning tool is recommended in these applications.  
Part number ACTAG02

### VERY IMPORTANT

Before joining the tractor, ensure the shaft is located correctly into the cover PTO hub before continuing. NEVER use the bell housing bolts to join the tractor. Sever damage to the clutch cover will result if these are not correctly aligned. Due to the internal design of the PTO drive, turning the shaft at the other end will not guarantee that the shaft will rotate at the cover hub.

When checking for possible cover damage during installation take note of the cover. Look for inward cover distortion towards the hub, generally in the three positions shown above. This is the result if the input shaft being allowed to push against the PTO hub.

Ag Clutch Australia will not accept any liability for any damage caused by incorrect fitment as shown and described above.

### LEADING BRANDS



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)