

TSB - DZ03

Models applicable > Deutz > D6006,6806,6807,7006,7007,7206 7207,7506,7807,8006,9006,10006

Details > when fitted with 290mm or 330mm dual sequential assembly Ag Clutch Part Numbers > 229 2502 DZ and 233 3101 DZ

FLYWHEEL MACHINING

Ag Clutch recommends complete clutch component replacement only including the correct restoration or renewal of the flywheel.



229 2502 DZ -36mm



233 3101 DZ -38mm

The flywheel step must be restored to the original negative step listed above to achieve correct plate release.

In the above applications the cover is designed to release the clutch plates sequentially allowing consistent PTO and main plate engagement.

Incorrect flywheel depth may cause the lever positions to change significantly thus resulting in incorrect release positions.

The clutch is factory set to suit original component specifications only.

Ag Clutch will not accept any responsibility for any loss or damage caused as a direct result of the flywheel not having been restored to original specification.



CLUTCH AND FLYWHEEL SPECIALISTS













